Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number Database(s) EPA ID Number

JH1333 MANHOLE #3707 NY Spills S106383418
NNW NW CRNR OF BAY PKWY/86 ST N/A

> 1 BROOKLYN, NY

1.697 mi.

8959 ft. Site 3 of 5 in cluster JH

Relative: SPILLS:
Higher Name: MANHOLE #3707

Actual: Address: NW CRNR OF BAY PKWY/86 ST

14 ft. City,State,Zip: BROOKLYN, NY Spill Number/Closed Date: 0313299 / 2004-06-04

Facility ID: 0313299 Facility Type: ER DER Facility ID: 93772 Site ID: 106438 DEC Region: 2 Spill Cause: Unknown Spill Class: C4 2401 SWIS: Spill Date: 2004-03-03 Investigator: **JHOCONNE** Referred To: Not reported Reported to Dept: 2004-03-04 CID: 73

Water Affected:

Spill Source:

Unknown

Spill Notifier:

Cleanup Ceased:

Cleanup Meets Std:

Last Inspection:

Not reported

False

Not reported

False

Not reported

Last Inspection:
Recommended Penalty:
UST Trust:
Remediation Phase:
Date Entered In Computer:

Not reported
False
O
2004-03-04

Spill Record Last Update: 2004-06-04
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: 001
Contact Name: ERT DESK

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was

O'CONNELL e2mis no. 152330: FOUND AN UNDIAPERABLE SHEEN OF UNKNOWN

OIL ON APPROX. 30 GAL. WATER IN VS-3707. SPILL APPEARS TO BE

CONTAINED. CLEANUP PENDING PCB RESULTS. 3-3-04 20:16HRS <1.0 PPM lab seq # 04-01598-001. UPDATE: PRESSURE TESTED VS-3707 AND PASSED. UPDATE: 3/4/04 - 1200 CLEANUP COMPLETED BY REMOVING LIQUID WASTE

USING COAG AND DOUBLE WASHING STRUCTURE WITH BIO GEN 760. SUMP FOUND

CEMENTED. TAG # 03682 REMOVED."

Remarks: "A SHEEN OF UNKNOWN OIL FOUND ON 30 GALS OF WATER IN A MANHOLE.

UNKNOWN IF TRANSFORMER INVOLVED (WILL CONDUCT A PRESSURE TEST FRIDAY). CLEAN UP PENDING. CON ED REF # 152330 SPILL IS COMING OFF THE 24 HOUR PROGRAM DUE TO THE FACT THAT THE UNIT HAS NOT BEEN

PRESSURE TESTED. "

All Materials:

 Site ID:
 106438

 Operable Unit ID:
 878537

 Operable Unit:
 01

 Material ID:
 498455

 Material Code:
 0066A

Map ID Direction Distance Elevation

Site

MAP FINDINGS

EDR ID Number
Database(s) EPA ID Number

Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: L
Recovered: .00

Oxygenate: Not reported